





FIG. 4-111 WIRING SKETCH


SCHEMATIC DIAGRAM



$\varphi \pm 0,5$
 $X : A \geq 1,2$
 $3 \geq 3,3$
 $2,5$
 $C \geq 4,5$
 $1/60^\circ \geq 15,3$
 $22,9 \pm 0,3$


EXPLODED ILLUSTRATION

$1^{st} > 0,5$
 $2^{nd} > 2,4$ } X



- KIT
- ENTRAINEMENT
- A61
 - O-C28-01
 - A2-C30-01
 - O-C33-02
 - A1-C34-02
 - C43-02
 - 44-01
 - O-C32-01
 - C105-01
 - O-C18-01


EXPLODED ILLUSTRATION




Product No. 23400

ASAHI PENTAX 6×7-5 Fig. 4

EXPLODED ILLUSTRATION




+ No 11 #
 + No 9 (●)
 + No 6 (●) nei 2x
 + No 1 -
 A03-01



ASAHI PENTAX 6×7-5 Fig. 1

EXPLODED ILLUSTRATION



Product No. 23400

ASAHI PENTAX 6x7-5 Fig. 2